Division of Health Care Facilities (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION COMPLETED STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 01 - MAIN BUILDING 01 AND PLAN OF CORRECTION A. BUILDING 6 WING 06/27/2011 TN1801 STREET AODRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 80 JUSTICE ST CROSSVILLE, TN 38555 LIFE CARE CENTER OF CROSSVILLE PROVIDER'S PLAN OF CORRECTION (X5)SUMMARY STATEMENT OF DEFICIENCIES COMPLETE (EACH CORRECTIVE ACTION SHOULD BE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX CROSS-REFERENCED TO THE APPROPRIATE DATE PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DEFICIENCY) TAG N 853 N 853 N 853 1200-8-6-.08(23) Building Standards A. What corrective action(s) will be accomplished (23) A negative air pressure shall be maintained for those residents found to have been affected: in the soiled utility area, toilet room, janitor 's On 7/13/11 an electrical company evaluated air closet, dishwashing and other such soiled pressure in dryer room for repairs to be 8/3/2011 spaces, and a positive air pressure shall be completed by 8/3/11. maintained in all clean areas including, but not B. How will you identify other residents having the potential to be affected by limited to, clean linen rooms and clean utility the same deficient practice and what corrective rooms. action will be taken? By 7/21/11 the Executive Director will complete education with Director of Environmental Services This Rule is not met as evidenced by: and Maintenance Assistant on negative air Based on observations, it was determined the 8/3/2011 pressure requirements. facility failed to maintain the negative air pressure C. What measures will be put into place or what systematic changes will you make The findings include: to ensure that the deficient practice will Observation of the laundry room on 6/27/11 at not recur? 1:18 PM, revealed the dryer room had had no The Director of Maintenance/Maintenance negative air presuure in the room. Assistant/Director of Environmental Services will conduct a monthly observation audit of laundry This finding was verified by the maintenance facility for three months to ensure negative air supervisor and acknowledged by the pressure is maintained in soiled linen area and administrator during the exit conference on positive air pressure is maintained in clean linen 8/3/2011 area. Corrections will be made as needed. 6/27/11. D. How will the corrective action(s) be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be put into place. Results of air pressure audit will be reviewed by Executive Director, Medical Director, Director of Nursing, Director of Marketing, Pharmacist, Director of Admissions, Director of Social Service. Rehab Services Manager, Director of Activities. Director of Environmental Services, Dietary Manager, Director Maintenance, Business Office Manager, Health Information Manager, and Staff Development Coordinator in Monthly QA meeting 8/3/2011 and corrections made as needed.

Division of Health Care Facilities

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Executive Director

7/15/11